

Photograph #1



View of placard for ID

Photograph #2



Left rear corner view

Photograph #3



View of rear panel from left side

Photograph #4



View of hour meter at time of inspection

Photograph #5



Serial number plate

Photograph #6



Overview of right side after recovery

Photograph #7



Undercarriage rear section

Photograph #8



View of structural damages to tunnel



Boom base damages

Photograph #10



View of damages to upper catwalk

Photograph #11



Crushed cab assembly

Photograph #12



Boom jib section

Photograph #13



Damaged base section of boom

Photograph #14



View of damages to rigging

Photograph #15



View of undercarriage just prior to uprighting