















Year model	2003
Last inspection	2017
Location	Finland
Availability	Today



Carrier		Superstructure	
	200 t		60 m
	10x6x10		Optional extra
	81.000 km		Heavy Lift 2 m
	16.00 x R25		
	Mercedes		Mercedes
	Allison		2 pcs
			80 ton - 12 ton
			18.100 h
			64 t

The vehicle is road inspected and superstructure is also inspected in Finland and is ready to work immediately.

Oversea transport will need one mafi and vehicle transportation. We are happy to make offer for that too!