

Year model	2009
Last inspection	2017
Location	Finland
Availability	Today



Carrier		Superstructure	
	100 t		MB OM 904 LA
	10x6x10		60 m
	~60.000 km		10/17 m 0 - 40°
	16.00 x R 25		1 pc
	Mercedes OM 502 LA		2 pcs
	DC G 240-16 - EPS		~11.500 h
			Full

The unit was inspected in Finland and she is ready to work immediately.